



SW - Model C






S035364_00

First Machine Check






Start Display (AT9+AT13)




2. Switch on control box




1. Switch on ignition










Activate Pump





Truck and trailer uses the same pump = 1000 rpm



During working time is the auxiliary engine runing at full throttle

= 2900 rpm






Let the machine run with the self-cleaning mode for one minute when the machine was not working for a longer time.

Container Filling






Filling with max. 1 bar



Open the vent valve before removing the filling hose!


Determination Bulk Density








Operation Set Up












Always press

the green marked keys

Always watch machine loading, it should be between 20% and 80%

Correction factor:









After spreading 5 -10min

Before first filling approx.1 min




Cleaning





Lubrication points







Streumaster Maschinenbau GmbH

84546 Egglkofen - Handwerkstrasse 1

Phone: +49 (0) 8639.608 0 Fax: +49 (0) 8639.608 51 E-Mail: info@streumaster.com

Service Hotline: +49 (0) 8639.608 555 E-Mail: <u>service@streumaster.com</u>